

No. 198.

John Fryer, Jan. 12th 1885.

Found old post to interior angle on S. E. of R. Reed don: T. 25 S. R. 5 W. still standing, but replaced by new one, also the post to exterior angle by a new one. Then traced section line

South: Var. $19^{\circ}10'$ E. to '4 post between sects. 8 and 9, reset '4 post, the remaining BT, being cut down, mark a laurel 30" in dia. bears $S 42^{\circ}3/4' W. 45$ lks.

South 20.00 chns, set post, from which a bl. oak 48" in dia. bears $N 40^{\circ}1/2' W. 57 1/2$

Trace South bdy of R. Reed don: from exterior angle

$N 78^{\circ} E$ to the intersection with a line South of '4 post between sect. 4 and 9; replace old post by new one.

See survey No. 22.

No. 199

J. Ellison and Alex. F. Brown

Winneford, febr. 28. 85.

Found NW corner rock, of R. P. Daniels don: T. 25 S. R. 6 W. correct by BT.

From corner, rock (set by Byars, but proved correct by me) of SW of Daniels don: run

North Var $19^{\circ}10'$ E. intersect Samer's SE corner 3 lks east of it.

No. 200.

B. F. Dowell, March 10. 85.

From West corner of Jesse Applegate don:

T. 22 S. R. 5 W. as set by the West BT,

$N 31^{\circ}26' E$. Var. 18° E. 76.70 chns to the NW corner.

at 16.62 chns set a bolt 16" \varnothing and 34" dia,

from which a bl. oak 48" h. $N 75^{\circ}3/4' W. 2 1/6$ chns

" bl. oak 36" h. $N 47^{\circ} W. 5.31$ "