

30-5

41.41 ch intersect west by line of
 Cl No 51. and set post for S.E. cor of
 Cl no 50 - from which W Oak 8 in dia
 bears N 94° W, 26 links

I then went to the N.E. corner of the
 N.W. 1/4 of the S.W. 1/4 of Sec 28. I so 25 m
 a point formerly established by me
 I then measured West 20.00 ch and
 reestablished quarter post between Sec

+

28 & 29. by setting a post 3 1/2 feet long, 2 1/2
 inches in the ground 4 in square marked
 1/4 S. C.S. from which R. Fir 8 in dia bears
 S 51° W, 66 links and marked 1/4 S. C.S. B.T.

and R. Fir 8 in dia bears S 68 1/2° E, 55 links
 marked 1/4 S. C.S. B.T. The original B.T. had
 been cut down, and burnt up by fire
 in brush fence I then measured and

C 1/4
 Sec. 29 →

run line S. 89° 45' W, 40.00 ch. Set post
 marked C.S. B.T. from which
 R. Fir 10 in dia bears S 56° E, 26 links
 W Oak 8 in dia " S 10° W, 10 "

No. 157

Survey made for Geo Dugg and Hardy & Cliff
 April 5th 1892. A Ramsey & A D. Strada
 Chaimmen. Beginning at 1/4 S Corner between

Sec 27 & 28 T 32 S. R. 6 W.

Set new post as per
 Original B.T. standing there - (var 18 45° E,
 40.00 ch. Set post marked C.S. B.T. from which
 W Oak 6 in dia bears N 10° W, 20 1/2
 Pin 10 in dia " S 70° E. 27 "

N 89° 54' W



Thence
 40.00 ch Intersect 60 links east of the original
 corner Set post marked 1/4 S. C.S. B.T. as per above
 tree the S. Pine was rotten and nearly gone
 made new B.T. to set R. Fir 8 in dia S 73° W, 24 1/2

South