

Set 1/4 post between 25 & 36 by B.I., Var 19° 5' E.

East 1.89 chms

South to South ldy of Atkins' don; mark boardfence.

From SE corner of Atkins' don:

West 74.54 chms. to mark on boardfence

From NE corner of Lane' don.

West 14.56 chms. to same mark.

From 1/4 post betw. 25 and 30. Var 19° 40' E

North 36.37 intersect meanderpost; thence

S 62 1/2° W 20.95 offset 945° E. 1.00 chms.

45 14.14. offset N 45° W. 100 chms. to line; set post from which  
39 3/4 14.94. a wh' fir 24" in dia bears N 20° W 65 lbs.

South Var. 19° 15' E. 44.97 intersect East of 1/4 post 1.22 chms

62.70 chms to South ldy at crossfence.


set post at mark of boardfence, from which

a dbl. bl oak 18" bears S 83 1/2° W 4.64 chms dist,

true line runs N 35 1/2° W.

No 214

Wm Russell May 30. 85.



T. 29 S. R. 9 W.

From 1/4 post between 12 and 7. Var. 19° 30' E.

N 89 3/4° W 19.94 chms. set post <sup>No 1</sup> from which

a fir 24" in dia. bears N 73 3/4° W 0.19 lbs.

N 89 3/4° W 39.90 chms. set post from which

a cedar 30" in dia. bears S 43° W 0.47 lbs

South 20.00 chms. set post from which

a fir 30" in dia bears N 29° E 0.16 lbs  
" 42" " " N 12 1/2° W 0.44

From post No 1.