

East

25-6)

a bend in Calabooia Creek. Thence  
30.50 ch that being the required distance  
called for by the original field notes  
thence offset South 5.00 ch. regained  
tree line at the S. E. corner of cl  
47 at this corner the original  
B.T. has been cut down, I made new  
post 4 feet long 4 in square above  
24 in in the ground (marked C 47.  
C.S. from which an Ash 12 in dia  
bears S 87° E. 22 links. (marked C 47. C.S.  
B.T.). Thence I run North on East  
boundary of C 47.

North

41-63 ch the distance called for by the original  
field notes one of the original  
B.T. Stanching marks plane exist  
No of cl had been omitted by the  
Dep Sur I put C 47 on the B.T.  
and establish the N. E. cor of cl  
47 by setting a post 4 feet long 4  
in dia square, 24 in in the ground  
(marked C 47. C.S. <sup>+ Rock beside 18 x 6 x 4 in</sup> from which  
original B.T. White Oak 18 in dia bears  
N 14° W. 299 link the original bearing was  
incorrect to wit N 25° W. 299 links  
the Black Oak called for was stand-  
ing but had no marks on it  
I blaze and mark the intended B.T.  
to wit Black Oak 20 in dia bears 1° E 370 links  
(marked C. 47. C.S. B.T.)

North

I then run  
3.00 ch set post 4 feet long 4 in square  
24 in in the ground (marked C.S.  
from which touch the same B.T.  
last above named as bearing trees  
for this corner to wit